



# 1 Axis Robot System

## WSP-1XSF 1 Axis Robot System (Finger Type)



- Main Voltage : 1 Phase AC 220~240V / 50/60HZ
  - 1 Axis Robot System
  - Mitsubishi AC Servo Driver & Motor
  - Sensor Type : NPN Type
  - Air is necessary for operation
  - Providing operation manual
- ※ P. L. C Controller is not included

## WSP-1XSV 1 Axis Robot System (Vacuum Pad Type)



- Main Voltage : 1 Phase AC 220~240V / 50/60HZ
  - 1 Axis Robot System
  - Mitsubishi AC Servo Driver & Motor
  - Sensor Type : NPN Type
  - Air is necessary for operation
  - Providing operation manual
- ※ P. L. C Controller is not included

01


02

03

04

# 2 Axis Robot System

## WSP-2XS 2 Axis Robot System



- Main Voltage : 1 Phase AC 220~240V / 50/60HZ
- 2 Axis Robot System
- Mitsubishi AC Servo Driver & Motor
- Sensor Type : NPN Type
- Air is necessary for operation
- Providing operation manual

※ P. L. C Controller & HMI are not included

## WSP-2XF 2 Axis Robot System



- Main Voltage : 1 Phase AC 220~240V / 50/60HZ
- 2 Axis Robot System
- Mitsubishi AC Servo Driver & Motor
- Sensor Type : NPN Type
- Air is necessary for operation
- Providing operation manual

※ P. L. C Controller is not included

\* Product's design and appearance can be changed without any notice.