P. L. C Application Equipment

WSS-4S Manufacture Process Trainer



■ Main Voltage : DC 24V

■ Digital Input & Output Connection Points

- Input: 17 & Output: 10

* P. L. C Controller is not included

■ Sensor Type : NPN Type

■ Air is necessary for operation

■ Providing operation manual

WSS-1S Pneumatic-Robot Trainer



■ Main Voltage : DC 24V

■ Digital Input & Output Connection Points

- Input: 13 & Output: 5

* P. L. C Controller is not included

■ Sensor Type : NPN Type

■ Air is necessary for operation

■ Providing operation manual

^{*} Product's design and appearance can be changed without any notice.