P. L. C Application Equipment

WSS-2N Manufacture Process Trainer



■ Main Voltage : DC 24V

■ Digital Input & Output Connection Points

- Input: 10 & Output: 6

* P. L. C Controller is not included

■ Air is necessary for operation

■ Sensor Type : NPN Type

■ Providing operation manual

WSR-3 Flexible Manufacturing System



- Main Voltage
- 1 Phase AC 220~240V / 50/60HZ
- Digital Input & Output Connection Points
- Input: 21 & Output: 9
- * P. L. C Controller is not included
- Sensor Type: NPN Type
- Air is necessary for operation
- Providing operation manual

^{*} Product's design and appearance can be changed without any notice.