P. L. C Application Equipment

WSR-6 Auto Storage System Trainer



- Main Voltage
- 1 Phase AC 220~240V / 50/60HZ
- Digital Input & Output Connection Points
- Input : 47 & Output : 15
- * P. L. C Controller is not included
- Sensor Type : NPN Type
- Air is necessary for operation
- Providing operation manual

WSR-6S Auto Storage System Trainer



- Main Voltage
- 1 Phase AC 220~240V / 50/60HZ
- Digital Input & Output Connection Points
- Input : 32 & Output : 15
- * P. L. C Controller is not included
- Sensor Type : NPN Type
- Air is necessary for operation
- Providing operation manual

01

02

03

 0^{2}